

SERVICE BULLETIN
1-800-237-0022

SUBJECT: Holland Fifth Wheel pin installation.

EFFECTIVITY: All new Holland load cell installations.

PROBLEM: Sometimes the fit between the knob on the load cell and the pocket in the fifth wheel is tight. This may make it difficult to insert the retaining pin through both fifth wheel ears.

SOLUTION: Grind a bevel on the end of the Holland Fifth Wheel pin as shown in Figure 1. When properly aligned, the bevel will compress the bushing in the knob. Use a hammer to drive the pin into place




Figure 1